

**Facility Incident Summary**  
**Safety-Kleen (NE), Inc.**  
*formerly: Laidlaw Environmental Services (North East), Inc.*

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
1-19-93	Spill	Warehouse	Nitric Acid Solution (MA99)	17E Metal	Drum grabbers punctured container while moving	No
1-29-93	Forklift fire	Warehouse	N/A	N/A	Transmission fluid leaked through a hole in a hose and was ignited by the hot engine. Employees extinguished with a Fire Ext.	Yes - DEP, Woburn and NRC #155665 and Fire Dep.
2-25-93	Leak	Warehouse	Flam. Liq; D001, F005	Metal 17E	Drum punctured with forklift.	No
2-25-93	Leak	Warehouse truck dike	unknown	Metal 37M	Drum arrived on a D&J truck leaking. No material released to the warehouse or dock.	No
3-9-93	Spill	Warehouse	1,1,1 Trichloroethane	Metal 17E	Drum fell off forklift, spilled 10 gallons. Cause determined to be forklift malfunction.	No
4-20-93	Reaction	Warehouse	Wastewater sludge	Metal 17H	Reaction occurred while combining sludge from a Dupont waste water load. After analysis, one drum on the load found to have a pH of 14.	No - no release
7-6-93	Spill	Warehouse	Flam Liq D001, D004 - 6	Metal 17E	Found leaking container upon morning inspection. 15 gallons released	No
7-8-93	Spill	Warehouse	Sulfuric Acid, Copper Sulfate	Metal 17H	D002,D006 waste drum, fell off the top pallet while being moved with forklift. Lid came off, 25 gallons released.	No
7-14-93	Leak	Warehouse	Unknown	Metal 17H	Laidlaw truck arrived at warehouse with leaking container. Approx. 2 gallon release to truck only.	No

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
7-26-93	Leak	Warehouse	Developer/ silver	Metal 17E	Found leaking container upon morning inspection. 25 gallons released.	No
8-2-93	Spill	Warehouse	Methanol/ Acetone	Metal 17H	Punctured drum with forklift. 1 gallon released	No
8-3-93	Reaction	Warehouse	Batteries	Metal 17H	Contacts on the batteries came in contact with the metal drum creating a charge which released Hydrogen (sulfuric acid present from some leaking batteries). Pressure built up in the container and the lid popped off.	Yes - DEP Woburn
8-5-93	Leak	Warehouse parking lot	Oil Waste	various	Residue from drums on the empty drum storage trailer leaked onto the pavement.	No
8-13-93	Spill	Warehouse	Etchant/ Water	plastic 55	Drum fell off pallet while being carried by the forklift. Released 20 gallons.	No
8-25-93	Leak	Warehouse truck dike	Oil Waste	N/A	Vacuum hose from an Oil Recovery truck came unclamped and released approx 1/2 gallon of truck oil to the dike area.	No
8-30-93	Spill	Warehouse	Methylene Chloride	Metal 17E	Forklift slid and punctured 2 containers with forks. 40 gallons released.	No
9-23-93	Leak	Truck at dock	Non Reg Ink	Metal 17H	Truck arrived with leaky gasket on drum. 4-6 oz. released.	No
9-23-93	Leak	Truck at dock	Isopropanol	Metal 17E	Truck arrived with leaking container. 1 gallon released.	No
9-27-93	Spill	Warehouse	Methyl Ethyl Ketone D001, F003,5	Metal 17H	Drum fell off pallet while being transported by forklift, top came off. 40 gallons released.	No
10-1-93	Flash	Warehouse	Ammonium Bifluoride (MA99)	17E metal	Small unsustained flash appeared while sampling (non reg waste). All sample rods will now be grounded.	No

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
11-1-93	Leak	Warehouse	Non-reg. ink	17H metal	Drum had bad gasket and material leaked on dock while off loading container (< 1 pint).	No
11-23-93	Leak	Warehouse	State reg. oil waste	17H	An empty containers was placed upside down in the MT storage trailer and approx 1 pint of residue leaked to the truck and to the ground.	No
2-7-94	Bulging drum	Warehouse	Flam. sludge	17H	Consolidated sludge (in-house) heated up due to some reaction of mixed sludge.	No
2-17-94	Drum flash	Warehouse	Acid sludge	POT	Acidic sludge sample containing metals flashed when being placed into a plastic sample bottle.	No
3-17-94	Leak	Warehouse	Flam. liquid	Tanker Valve	Hose-valve connection leaked about 1/2 gallon flam. liquid while pumping load. Material didn't exceed RQ and was cleaned up immediately.	No
4-25-94	Leak	Warehouse	Non-regulated Material	17E	Container of Boric Acid solution was noticed leaking when unloaded and placed on loading dock. No release to the environment.	No
5-11-94	Spill	Warehouse	Corrosive Liquid	15CB	Container of Hydrochloric acid was wedged between two larger containers on truck. When off loaded, the container cracked. Contents released to loading dock. No release to the environment.	No
6-6-94	Spill	Warehouse	State regulated oil waste	Sample bottles (3 oz)	Approximately 20 plastic sample bottles fell off the back of a truck at the loading bay. Approximately 2 oz. of material spilled onto ground and was cleaned up immediately	No
6-27-94	Leak	Warehouse	Oxidizer, Corrosive material	5 gal ppl	Approximately 1 pint of an oxidizing, corrosive material leaked from a 5 gallon pail due to a hole puncturing the container while on a pallet. No release to the environment.	No
7-5-94	Leak	Warehouse	Toxic material - D007	17E55	A 55 gallon container separated at the bottom stream and released contents. Material was immediately cleaned up. No release to the environment. Injury report completed for employee (Tim Grimes) splashed with material.	No - no release to environment.
7-20-94	Leak	Warehouse	Flammable liquids	Tanker truck	Franklin Env. tanker truck started to leak at the shut-off valve. Material in tanker was pumped into another tanker in next loading bay.	Yes - release no. 3-1130

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
7-21-94	Leak	Warehouse	State regulated oil waste	17H55	A pint of oil waste leaked out of the top bung hole of a 55 gallon drum when off-loaded. No release to the environment.	No
8-4-94	Spill	Warehouse	Flammable Flux	17E55	About 30 gal. of flux spilled when the drum slipped out of the drum grabbers and the top of the drum split open. No release to the environment.	No
8-8-94	Spill	Warehouse	Alkaline liquid D002, D007	PC55	About 1 qt. of alkaline liquid spilled when the drum slipped off a pallet when being unloaded. Less than 1 qt. of material leaked into the dike. No reportable quantities were exceeded.	No
8-10-94	Leak	Warehouse	Nitric acid D002, D008	PCH	While trying to break a drum strap off a pallet, the wire cutters gouged the container and 15 gallons of material leaked. No release to the environment.	No
8-12-94	Spill	Warehouse	Chromic Acid D002, D007	PC55	Container slid off pallet when being placed in acid dike. Top of container cracked releasing 50 gal. of material to the acid dike. No release to the environment.	No
8-30-94	Spill	Warehouse	HWL; D007, D008	PC85	Container slid off pallet when being moved and dropped to floor. No release to the environment.	No
9-15-94	Equipment Fire	Warehouse	Flammable Solvents	NA	An activated carbon unit built up heat through friction. A backflow in this unit created a flash and fire. Unit has been taken out of service.	Yes - DEP Woburn
10-10-94	Leak	Warehouse	Non-Regulated Material	Roll-off	Roll-off received at facility leaked non-regulated material once backed down into loading bay.	No
12-15-94	Spill	Warehouse	Non-Regulated Material	PC55	Container slid off pallet when being moved and dropped to floor. No release to the environment.	No
1-8-95	Release	Warehouse	HWL; D006, D007, D008, D009	17H55	Container built up pressure and released material through top. No release to the environment.	No
1-12-95	Spill	Warehouse	Flammable Solvent	Tanker	Vehicle temporarily lost pressure. Approx. 1/2 gallon of material leaked into loading bay. Material was cleaned up immediately. No RQs were exceeded.	No

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
1-30-95	Leak	Warehouse	Formaldehyde	17E55	Fork truck driver punctured drum with drum grabber. Material wasking lot. Material was cleaned up immediately. No release to environment.	No
4-28-95	Spill	Warehouse	Non-Regulated Material	17H55	Container slid off pallet when being moved and dropped to floor. No release to the environment.	No
5-30-95	Spill	Warehouse	Non-Regulated Material	PC55	Container slid off pallet when being moved and dropped to floor. No release to the environment.	No
6-28-95	Heated Drum	Warehouse	Corrosive	6D	Drum was noted under pressure during daily inspection. Drum was isolated, re-sampled, analyzed, and allowed to vent for 12 hours. No release to the environment.	No
6-30-95	Spill	Warehouse	Metal Hydroxide Sludge.	CF220	Wrangler slid off pallet when being off-loaded. Material spilled out of container in the truck. Material was cleaned up. No release to the environment.	No
12-11-95	Spill	Warehouse	Non regulated Material	55 POT	Drum slid off pallet while pallet was being removed from a row. Material was cleaned up. No release to the environment.	No
5-20-96	Leak	Warehouse	Flammable Liquid, Corrosive	55 PC	Drum was punctured by the blade of a fork truck causing the contents of the drum to leak on the floor. Material was cleaned up. Drum was overpacked. No release to the environment.	No
5-29-96	Fire	Warehouse	Lead Acid Battery	Battery on pallet	Battery was stacked on a pallet, separated by a layer of cardboard from other batteries. Wires were not separated properly. Wires touched, causing a spark and subsequent smoking of the cardboard and duct tape.	No
6-7-96	Heated Wrangler	Warehouse	State Regulated Oil Waste	Cu Yd. Box	Drums of state regulated oil waste were consolidated into a wrangler. One drum was activated carbon, which heated up upon contact with contents of other drums which were moist. Steam was released. Wrangler did not bulge.	No.
7-9-96	spill	Warehouse	Flammable Liquid	5517E	Drum was punctured by blade of forktruck, causing contents to leak on the floor. Spill was cleaned up. No release to the environment.	No.

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
9-6-96	Heated Drum	Warehouse-LPC Room	Inorganic Salts	5517H	Upon consolidation of Solids in the consolidation booth, technician put incorrect materials into a drum, which started to heat up. Consolidation activities were stopped, and speedy dry was added to the top of the drum until it had cooled off.	No.
9-10-96	Leak	Warehouse	Waste Water	Bulk Tank truck	Upon pumping of water waste onto a vacuum truck, it was noted that a very small amount of an orange vapor was leaking from the fitting where the tanker hooks up to the vapor recovery system. Pumping was stopped immediately	No.
11-22-96	Leak	Warehouse	Oil	Empty Drum Trailer	Oil was dripping out the side door of the empty drum trailer, approximately 1 pint. Spill was cleaned up. The trailer was emptied of its contents and floor was cleaned.	No.
1-17-97	Spill	Warehouse	Hazardous waste Liquid	55PCH	While arranging drums on a pallet, a drum being moved by drum grabbers slipped out of the grabbers and fell over. Approximately 35 gallons spilled. Spill was cleaned up.	No.
2-19-97	Bulging Drum	Warehouse-LPC Room	Lean Water	55 1A2	Approximately two hours after consolidating lean waters in the LPC room, technician noted the drum was bulging and venting through the bolt. Drum was allowed to sit in the booth until reaction was complete.	No.
4-4-97	spill	Warehouse	Boric Acid/Water	TP330	While offloading a 330 gallon tote, the pallet that the tote sits on broke, causing the tote to tip over. Material spilled inside the truck and approximately 1 gallon spilled in the loading dock area. Material was cleaned up immediately.	No
4-19-97	Spill	Warehouse	Corrosive	551A2	While picking up drum with grabbers, the top came off spilling the liquid on the main floor. Spill was cleaned up. No release to the environment.	No
5/7/97	Spill	Warehouse	Ethyl Acetate	37M	While offloading a truck in the offloading area, a blade from the forklift punctured a drum, spilling the contents of the drum in the dike. The spill was a 21E RQ spill because of the volume of ethyl acetate. Material was cleaned up immediately.	Yes MA DEP
6-23-97	Spill	Warehouse	Non-Regulated	Fiber, OH	While offloading a pallet of waste, pallet fell apart, causing 15 gallons of	No.

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
			Material		material to spill in the dike. Spill was cleaned up.	
7-17-97	Spill	Truck in Loading Dock	Non-Regulated Material	50 gallon Fiber	While rolling drums onto pallets, bottom of drum cracked, releasing approx. 5 gallons on floor of truck. Material was cleaned up with speedy dry. Spill was totally contained in truck.	No.
8/25/97	Flash	sample in Flammable Storage Area	Ethanol/Methanol mixture	150 ml sample bottle	While releasing the contents of the sample rod into the sample bottle, the material flashed and a candle-size flame was sustained in the mouth of the sample bottle. Flame was blown out. Facility will utilize "anti-static" sample bottles for sampling of flammable materials.	Yes DEP Woburn
9/18/97	Spill	Warehouse	Corrosive Liquid 5-15% Sulfuric Acid	Plastic Closed top Drum	While loading a truck, plastic drum slipped from drum grabbers, leaking approx. 1 gal material inside facility. Spill was cleaned up with speedy dry.	No.
10/6/97	Spill	Alkaline Dike	Sodium Hydroxide Solution	Plastic Open Top Drum	While moving pallets between rows in the alkaline dike, one of the drums fell off the pallet, spilling its contents. All material was contained, and cleaned up with speedy dry. 50 gallons released.	No.
11/4/97	Spill	Dike in Loading Area	Dirt w/Acetone, Methanol, MIBK, Xylene, Toluene	Wrangler	Wrangler was found to be leaking on outgoing load truck that was parked in the loading dike. 1 quart was spilled onto dike. No RQ was exceeded.	No.
11/17/97	Spill	Truck in Loading Dock Area	Non Regulated Material	Plastic Closed Head Drum	While picking up drum with forklift grabbers, the drum split open. Estimated 5 gallons were spilled inside the truck. Nothing released outside the vehicle. No RQ exceeded.	No.
12/17/97	Flash	General Staging Area	Non Regulated Batteries	30 Gallon 1A2 Drum	While sampling a drum of managanese dioxide batteries, a handful of batteries were grabbed and a flash occurred. No Release.	No.
2/10/98	Leak	Truck in Loading Dock Area	Non Regulated Dye	2 x 85 gallon overpack drums	The facility received two 85 gallon overpack drums that were rusted on the bottom. As the drums were being offloaded from the truck, the containers leaked, spilling approximately 2 gallons into the truck and ½ gallon into the truck dike. No RQ Exceeded.	No.
3/11/98	Fire	Solids	Debris	Cubic Yard	Warehouse personnel were consolidating 12 drums of debris into 3 cubic	Yes.

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
		Consolidation Room	Contaminated with Arsenic, Phosphorous, Graphite	Box	yard boxes. After consolidation was complete, one of the wrangler's contents caught fire. Two workers immediately extinguished the fire. The cause was determined to be the presence of red phosphorous, which the generator had not profiled, along with the air dispersion of the powder during the process which ignited and caught the debris on fire.	
5/15/98	Small Flash	LPC Room	Labpack Glass bottles with Water, Zirconium, Aluminum Metal Powder	Labpack Drum	Glass bottles from labpacks were being consolidated in the LPC room. After compatibility testing, the LPC technician began pouring the material into a new consolidation drum. As one of the glass bottles was placed into the funnel, a flash occurred. There was no fire. Consolidation was immediately stopped. The remainder of the labpack bottles were repacked into labpack containers and routed for incineration. An accident investigation was conducted. No release.	No.
6/10/98	Spill	Acid Dike	Sulfuric Acid	1H1Plastic Closed Head Drum	A pallet of drums were being moved in the acid dike. A drum fell off the pallet, spilling 3-4 gallons in the dike. Spill was immediately cleaned up with speedy dry. Not a reportable release.	No.
06/30/98	Reaction	Alkaline Dike	Aluminum Pods w/KOH	Fiberboard Box	A pallet of small boxes containing aluminum pods began smoking while in storage. The pods were contained in fiber boxes that were crushed under the weight of other boxes on the pallet. KOH inside the pods reacted with the aluminum packaging to release water vapor and hydrogen. Generator contacted regarding chemical reaction, pallet was broken apart to reduce weight. Reaction stopped on its own. Not a reportable release.	No.
9/998	Spark	General Staging Area	Non-regulated battery	1A2 drum	A drum of batteries was being sampled upon receipt. The battery removed from the drum was too large for the standard sample bottle. The warehouse person in error tried to dismantle the battery so that it would fit in the container, instead of getting a larger container. This created a spark. No reaction or fire occurred.	No.
9/21/98	Reaction/Imminent Fire	LPC Room	Oxidizer Labpack	30 gal Fiber Drum	Two warehousemen noticed a labpack in the oxidizer dike that was leaking. The labpack was brought into the LPC room to overpack. The process of overpackkng the container caused a small spill on the floor. The warehousemen used speedy dry to clean up the spill, and then placed the speedi dry into the overpack container with the leaking labpack. The	Yes.



Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
					speedi dry reacted with the spilled oxidizers, creating a smoking drum. Facility contingency plan was implemented.	
11/19/98	Flash	Staging Area	Water w/organics	Plastic Closed Head Drum	While sampling a drum of water waste liquid, a flash occurred upon release of material into the sample bottle. There was no sustained fire. Upon investigation, the waste had a top layer of heptane (flammable). The sample bottle chosen was not a static-proof bottle because the waste was not identified as flammable. SOP was changed to utilize static-proof bottles for all waste for sampling.	No.
11-25-98	Reaction	Solids Consolidation Room	Debris w/gasoline, ethyl acetate, .2% trichloro-isocyanuric acid	1A2 Open Head Drum	Three drums of debris with organic solvents were compacted around 10 am on 11/25. Approximately 10 hours later, pressure buildup in the drum popped off the top and smoke began billowing out of the drum. Upon investigation, residue on certain debris from one generator reacted with contamination on debris from a different generator. No fire, however, enough smoke to implement the contingency plan. No release to the environment.	Yes.
2/18/99	Leak	On TriState Truck in Dike	State Regulated Oil Waste	1A2 Open Head Drum	A TriState truck delivering a load of containers from the Syracuse transfer facility, was found to contain a drum with a pinhole leak on the truck. 1 Gallon was spilled on the truck floor. No release to the environment. Spill was cleaned up immediately.	No.
3/4/99	Leak	General Staging Area	Metal Hydroxide Sludge	Cubic Yard Box	A cubic yard box was received from a customer identified as solid metal hydroxide sludge. While moving the container to the storage area, it fell off its pallet, spilling 2 gallons of liquid. Spill was immediately cleaned up.	No.
3/10/99	Small Reaction	Solids Consolidation Area	Flammable Sludge	1A2 Open Head Drum	Consolidation of sludge from a flammable liquids load was occurring in the solids consolidation area. A warehousemen mistakenly combined a sludge with a pH of 10 from another load into the drum and the drum heated up slightly. Drum remained closed and did not build up pressure. No release.	No.
5/7/99	Spill	General Staging Area	Non Regulated Water based Emulsion	55 Open Top Fiber Drum	A pallet was being removed from a second tier in a general staging row when the fiber drum on the pallet fell off. Approximately 30 gallons spilled onto the concrete floor. Spill was immediately cleaned up.	No.

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
5/11/99	Spill	LPC Room	Flammable Solvent Mixture	55 gal 1A2	After consolidating labpacks into a bulk container, the bulk container began to build up pressure. The warehouseman tried to crack the bung of the drum which caused a small 4-6 oz spill on the floor of the LPC room.	No.
5/17/99	Spill	Loading Dock	Flammable Lean Water Bulk Load	Vacuum Truck	After completing the loading of a tanker truck, the driver failed to shut the valve of the truck before shutting down the motor. Because there was a stick in the valve, the valve failed to close before vacuum was lost on the tanker. Approximately 2-3 gallons of liquid spilled onto the loading dock. Two warehouse workers squeegeed the spill and the hose of the vac truck was used to re load the material onto the tanker. SOP was corrected to ensure that the valve closes before the motor is shut down.	No.
06/02/99	Spill	Main Aisle-Staging area	F006 plating sludge	CF220 (cy box)	A cubic yard box was received from a generator inside a plastic bag. While attempting to overpack the wrangler, the container rolled onto its side, spilling 5 gallons of liquid. Spill was immediately picked up and container was overpacked.	No.
06/30/99	Spill	Truck	Flammable liquid	1A2 (55 gal drum)	While loading a split outgoing load, the forklift operator punctured a 55 gallon drum while loading a cubic yard box right in front of it. Approx 1 gal liquid spilled on the inside floor of the truck. Spill was immediately picked up and container was overpacked.	No.
8/4/99	Spill	Loading Dock	State Regulated Oil	1A2	While loading a truck, a drum was picked up to place on the truck when the lid popped off the container, spilling 4-8 ox material on the floor. Spill was immediately picked up and overpacked.	No.
9/21/99	Spill	Main Aisle, area C	Paint Related Material	1A2	While moving a container from the loading dock to the flammable storage room, a pallet cracked, causing a 55 gallon drum to spill its entire contents. Material was immediately diked and cleaned up, generating 3x55 gallon containers.	No.
9/27/99	Spill	Area C	Non Regulated Material	1A2	While pulling a pallet from a row, the pallet cracked causing the drum to fall and spill 30 gallons. Material was immediately diked and cleaned up.	No.

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
12/1/99	Pressurized Container	Truck Dike	Acid Sludge	1H2	While unloading a container from a truck onto a pallet, the container's cover flew off and hit a warehouseman in the face. Approximately 1 oz of material was released to the floor of the truck. No release to the environment.	No.
1/7/00	Spill	Staging Area	Hazardous Waste Liquid, nos (F002,D039,D040)	85 Gallon overpack	While pulling drums from a row, an overpack container, banded together on the pallet, fell off the pallet, spilling approx. 20 gallons of material on the floor.	No.
4/26/00	Spill	Truck Dike	Non-Regulated Material	1A2 (55 gal)	While backing into the truck dike with the door open on the trailer, Trism's load lock came loose, and a drum fell into the dike. Approx. 2 gallons of non-regulated material spilled into the dike.	No.
5/11/00	Fire	Truck Dike	Exhaust Hose on Tank truck	Tank Truck	At the end of a pump load (Lean Water), the driver and a warehouse worker both noticed the exhaust hose smoking. It then started burning. Warehouse worker immediately extinguished the flame. Contingency plan was implemented.	Yes.
6/4/00	Leak	Row 17 Storage Area	Non-regulated Evaporator Sludge	20x 1A2 (55 gal)	At the start of a shift, the shift supervisor noticed several drums leaking in Row 17. The material, although labelled non-regulated material, had sulfuric acid in it, which corroded the drums. Approximately 45 gallons were released to the floor. The spill was immediately picked up and all containers were overpacked.	No.
6/27/00	Spill	Acid Dike	Ferric Chloride	55 gal plastic closed top drum	While placing drums into storage, a warehouse worker placed a pallet of 4 drums on top of a pallet with three drums. This caused the top pallet to be unstable, and a drum from the top pallet fell over in the dike. When this was discovered, approx. 30 gallons of Ferric Chloride had spilled inside the acid dike. The spill was immediately picked up and container was overpacked.	No.
8/14/00	Leak	Acid Dike	Phosphoric Acid Solution	55 gal 1A1	While conducting a morning inspection of the warehouse, the supervisor noted a leaking container in the acid dike. Shift employees immediately cleaned up the spill and overpacked the container. Approx. 10 gallons of material had leaked into the dike.	No.

Date	Incident Type	Location	Material Involved	Container Type	Description	Reportable
10/3/00	Spill	Row 20 Storage Area	Evaporator Sludge D008	55 gal 1A2	While moving a pallet from row 20 to row 19, the pallet broke, and a drum fell from it, spilling 1 gallon of liquid. Employees immediately cleaned up the spill and overpacked the container.	No.
1/22/01	Pressurized Container	Row 14	Solids containing acrylamide	30 gal drum	During a routine inspection, a drum in Row 14 appeared to be under pressure. Drum was lowered from third tier and was discovered to be missing the bung. A vented bung was placed on the container. No release. Profile was made inactive.	No.
4/25/01	Spill	Loading dock	Flammable Liquid	Bulk vacuum truck	A bulk load destined for Bridgeport, NJ began pulling out of the truck dike after being released, and material sloshed from one of the hatches on top of the tanker into the dike. Approx. ½ gallon spilled. The hatch was <b>not</b> the opening that the waste had been loaded into or used for sampling. RQ's were evaluated and the material was cleaned up.	No.
4/27/01	Fire	Solids Consolidation Area	Debris/Glass/Rare Earth Metals	Cu. Yd. Box	During consolidation of solids, a small fire started that was quickly extinguished by the warehouse personnel. Contingency Plan was implemented. Investigation followed. Fire was caused by material in a 5 gallon pail that was not indicated on the profile.	Yes.
6/8/01	Odor Release	Area A	Carbon/Benzene and Toluene	Carbon Tank	During transfer of material from the tank into a cubic yard box, vapors were released which caused odor complaints from people working on the 2 <sup>nd</sup> floor of the facility. Operation was immediately halted and ventilated. Investigation supported by company IH revealed that the concentration of the solvents were well below OSHA PEL.	No.
7/17/01	Spill	Loading dock	Corrosive Liquid	55 gal drum.	During loading of a truck, warehouseman lifted a pallet with a forklift and one of the drums on the pallet fell off, releasing 4-8oz. of fluid. No release to the environment. Material was immediately picked up.	No.
7/24/01	Spill	Acid Dike	Sulfuric Acid	55 gal drum	While pulling drums in an acid dike row, one drum fell off a pallet, cracking the drum to crack on top and releasing 1-2 gallons of material. No release to the environment. Spill was immediately cleaned up.	No.

